



Release Notes for Red-M Blade Bluetooth Module for Visor

Introduction

The Red-M Blade Bluetooth Module for Visor CD provides software and documentation for use with the Red-M Blade Bluetooth Module for Visor.

The current release of software is compatible with any Handspring Visor PDA running PalmOS 3.5.x, e.g. the Visor Prism, Edge, Pro, Neo or Platinum. Handspring Visor devices running PalmOS 3.1 (e.g. Visor, Visor Deluxe) are not currently supported.

Additional Undocumented Features

This release of software installs an icon for the Red-M Bt Manager on the applications screen, visible in the 'All' and 'Bluetooth' application categories. This icon is a shortcut to the Bluetooth preferences panel, and allows quick and easy access to the Bluetooth configuration for the Visor module.

Workarounds for known issues in Release 3.2

This release has been designed and tested to work reliably in typical customer use. Listed below are some observed issues and workarounds for this release.

- 1) If the user performs a hard reset on a Visor PDA while the Blade module is inserted, the PDA will not allow the initial configuration (country, time settings) to complete. The module should be removed if a hard reset of the PDA is necessary.
- 2) If two Visor PDAs are to be configured to connect to each other using Bluetooth authentication and/or encryption, the user must ensure that the PIN numbers match on each device. Using non-matching PIN numbers may cause a software error requiring a soft reset of the device.